TYPE-CASTING MACHINES.

FOR GAS OR FUEL, COMPLETE.

WE place these Type-Casting Machines before the Trade with confidence. They will rank second to none for durability and workmanship. Every care has been taken to make these Machines complete, and only the best material is used in building, while, to facilitate repairs at any time, all parts are made interchangeable. We guarantee all our Machines, Tools, and Matrices. By using our breaking-off moulds with non-rubbing matrices, type equal to that of the leading type-founders can be produced, labour and space saved, and all profits appropriated by the user.



This illustration represents hand power only.



This illustration represents hand and steam power.

PRICES:

For Small Work, hand power only	£40	0	0
,, ,, hand or power	45	0	0
For Large Work, hand power only	45	0	0
,, ,, hand or power	50	0	0
Slow Gear attached to either size Machine	9	9	0

COMPLETE TYPE-CASTING OUTFIT, for one size body.

One small work Type-Casting Machine for hand power	£40	0	0
One set of Tools for same	0	15	0
Gas Burner, Fume Box, and Piping ...	1	1	0
One Mould to cast Type that requires no rubbing	3	10	0
One Mould to cast Spaces that require no rubbing	3	10	0
One Mould to cast Quads that require no rubbing	3	10	0
These Moulds cast from Pearl size to English; for larger sizes see next page.			
One Dressing Bench	6	15	0
One Dressing Rod	2	0	0
One Dressing Plane with two Cutters	1	13	6
One Turning Gauge	1	12	6
One Height to Paper Gauge, with Height to Paper Steel	1	10	6
One Lining Gauge	1	1	0
One Bodying Gauge, 12 ems deep ...	0	18	0
One Paging Iron	£0	6	0
Two Paging Galleys	0	17	6
Half-gross of Setting-up Sticks ...	1	18	0
One Fount of Roman Matrices, containing 143 at 4/6 each, for non-rubbed Type...	32	3	0
1 fount Roman Matrices comprises—low. 34, caps. 28, small caps. 28, points 10, figs. and £ 11, rules 5, references 6, braces 3, middle and corner 3, signs 15, space and quad mats. 9.			
One Fount of Italic Matrices, containing 79 at 4/6 each, for non-rubbed Type...	17	15	9
One fount Italic Matrices—low. 44, caps. 28, figs., £ and $ 12, points 5.			
Kerning Machines, Improved, with File	4	0	0
Total	£126	8	9

The No. 1 Machine will cast from the smallest type up to 2-line Pica.

Matrices and Moulds made to any Founders' standard or for point system at same prices as above.

NOTE.—It is desirable to have an extra set of Nipple, Jobber, and Plate, price 15/6. Where rules and braces are required to be cast, a Rule Mould is necessary, price £3 10s. The Machines are made with heating apparatus for melting the metal, either for gas or fuel, as desired.

FOR LARGER OUTFITS SEE ADDITIONAL APPLIANCES NEXT PAGE.